

CWS32-H01-VR - Technical Notes

Rev. 1.1 - July 2007

Even if the Paperless Recorder VR06CR & VR18CR could be equipped by a serial port RS232 – 485 in addition to the Ethernet Port, the expected and suggested connection To be used to connect the instrument to the software CWS32-H01 is in any case the Ethernet port

To avoid communication problems, it is necessary to use the following kind of Cables for the connection:

In case the connection would be direct between the recorder VR06/18CR and The PC network board, the cable to be used must be a CROSS sort

While in case the connection of the instrument comes through a structured network Or a HUB – Switch, it is necessary to use a normal network cable, that is not a CROSS